Concept Question 4-11: How do we compute the steady-state step response without performing partial fraction expansion?

Using the final-value theorem of the Laplace transform, the steady-state step is $\mathbf{H}(0)$, where $\mathbf{H(s)}$ is the transfer function. See the text above Eq. (4.156).